

CERCLA REMOVAL ACTION DAILY WORK ORDER

DAILY WORK ORDER

RESPONSE LOCATION (SITE NAME
AND/OR ADDRESS AND ZIP CODE)

CONTRACT NO.

ORDER NO.

M PF Am Site
E. Rutherford NJ

68-52-2101

2101-02-028

DATE

3-15-99

SHIFT

SITE/SPILL NO.

LW

EPA REGION/USDG DIST.

II

ON-SCENE COORDINATOR

PAUL KAHN

CONTRACTOR

ETI

CONTRACTOR RESPONSE MANAGER

KEVIN SHAVER

1.

N/A

MONITOR(S)

2.

DESCRIPTION OF WORK TO BE PERFORMED

1. Hold H+S meeting with owner

2. Continue to empty plating tanks - down and stage inside premises
in Longway building area

3.

NUMBER OF PERSONNEL AUTHORIZED

...1...SUPERVISORS

...1...FOREMAN

...1...OPERATORS

...7...LABORERS

...2...OTHER (SPECIFY) P.C.T., Chemist.....

4.

EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED

ITEM	QUANTITY	ITEM	QUANTITY
all from previous day			
/		/	

I CERTIFY THAT THE ABOVE WORK IS ORDERED AND
AUTHORIZED BY THE CONTRACTOR IN THE PER-
FORMANCE OF THE ABOVE CITED DELIVERY ORDER.

I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.

SIGNATURE OF OSC

Paul Kahn

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE

Kevin Shaver

AMENDMENTS (INCLUDE TIME AND AUTHORIZING PERSON)

SIGNATURE OF OSC

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE

ORIGINAL

442534

